

CONDITION REPORT

EXCAVATOR

Basic Information			
Maker	KOBELCO	Model	SK135SR-2
Serial No.	YY06-18105	Year	2012
Hours	5288	Travel distance	
E/G MODEL		COUNTRY OF ORIGIN	
Specifications	CAB,A/C,500G-PAD,CRANE,MULTI		

- A : Brand new
 B : Very good condition for its hours and year, or it has been repaired.
 C : Fair condition for its hours and year.
 D : Workable but remarkably deteriorated with age. Repair or replacement is necessary.
 E : Not workable. Replacement is necessary.

Check points		Comments
Exterior		
Exterior - left front&rear	C	
Exterior -right rear &front	C	dent
Exterior - each cover	C	
Operating seat		
CAB/CANOPY	C	
Control lever	C	
instrument panel.	C	
Internal devices, switches	D	Air conditioner temperature does not rise
Hour meter	C	
Other remarks	D	seat torn
Engine		
Oil leak, fuel leak	C	
Noise	C	
Exhaust gas	C	
Cooling system	C	
Muffler	C	

Check points		Comments
Battery	C	
Hydraulic System		
Valve	C	
hose, pipe	C	
Pump	C	oil smear
Tank , Oil-cooler	C	
Swing table		
Swivel bearing	C	
Swivel motor	C	
Swivel joint	C	
Boom &Arm		
Boom	C	
Boom cylinder	C	
Arm	C	
Arm cylinder	C	
Bucket cylinder	C	scratch in rod
Bucket	C	worn out
Bucket link	C	worn
Crawler type undercarriage		
Left link bush	C	
Left drive sprocket	C	
Left front idler	C	
Left upper roller	C	
Left lower roller	C	1pc worn
Left shoe, pad	C	
Left final, travel motor(cover)	C	

Check points		Comments
Right link bush	C	
Right drive sprocket	C	
Right front idler	C	
Right upper roller	C	
Right lower roller	C	
Right shoe, pad	C	
Right final, travel motor(cover)	C	