

## INSPECTION REPORT for Excavator 検品書 (油圧ショベル)

Maker	KOBELCO		Model	SK135SR-2			Serial	YY05-12833	
Year	2008	3	Hour	8,545	hr/	OK	BKT/ATT	Bucket	Without BKT
Shoe	500	mm	St	eel+PAD	Piping	C	Crushe	r and Breake	er piping
Multi Control	Multi				Air Conditioner	AC			
Dozer	_	ID key	_		Crane	With			
Operator Seat	CAB				Accessories				
Specification				_					

	Subject	Condition	Subject	Condition
Engine	Start/ Stop	Χ	Accell	Χ
	Output	Х	Sound	Х
	Exhaust Gas	Χ	Oil Leakage	Х
	Blow-by Pressure	Х	Fuel Leakage	Х
	Radiator	Χ	Oil	Χ
Undumilie	Pump Output	Х	Control Valve	Х
Hydraulic	Sound	Х	Oil Cooler	Х
Cont	Swing bearing/ Gear	X	Swing Reduction Unit/ Motor	Х
Swing	Swivel Joint	Х	Swing Reduction Unit Oil	Х
Attachment	Boom	X	Boom cylinder (Left)	Х
	Arm	Χ	Boom cylinder (Right)	Х
	Attachment	Looseness	Arm cylinder	Х
	Swing/ Offset	_	Bucket cylinder	Х
	Dozer	_	Swing/ Offset cylinder	-
			Dozer Cylinder	-
Operation	Operation lever	Х	Boom	Х
	Travel lever	Х	Arm	Х
	Swing	Х	Attachment	Х
	Travel	Х	Swing/ Offset	-
	Retracted Crawlers	_	Dozer	-
Undercarriage (Left)	Shoe	Х	Crawler Frame	Rusty
	Link / Bushing	Wear moderately	Upper Roller	Х
	Idler	Х	Lower Roller	Х
	Travel Reduction Unit/ Motor	Х	Sprocket	Х
Undercarriage (Right)	Shoe	Х	Crawler Frame	Rusty
	Link / Bushing	Wear moderately	Upper Roller	Х
	Idler	Х	Lower Roller	Х
	Travel Reduction Unit/ Motor	Х	Sprocket	Х
Electrical equipment	Error	X	Gear Change	Х
	Monitor	Χ	Battery	Х

Important Notice

scratch on the serial number plate revolving light missing crane hook looseness