

## INSPECTION REPORT for Excavator 検品書 (油圧ショベル)

Maker	KOBELCO	Model	SK200-8		Seria	YN11-	YN11-52016	
Year	2008	Hour	8,276	hr/	OK BKT/A	Bucket	Without BKT	
Shoe	600 mm		Steel	Piping		_		
Multi Control	Multi			Air Conditioner	AC			
Dozer	ID key	With (W	ithout master)	Crane		With		
Operator Seat	CAB			Accessories				
Specification								

	Subject	Condition	Subject	Condition
Engine	Start/ Stop	Χ	Accell	X
	Output	Х	Sound	Х
	Exhaust Gas	Х	Oil Leakage	X
	Blow-by Pressure	Χ	Fuel Leakage	X
	Radiator	Χ	Oil	X
Hydraulic	Pump Output	Х	Control Valve	X
	Sound	Х	Oil Cooler	Х
	Swing bearing/ Gear	Х	Swing Reduction Unit/ Motor	X
Swing	Swivel Joint	Х	Swing Reduction Unit Oil	X
Attachment	Boom	Looseness	Boom cylinder (Left)	X
	Arm	Χ	Boom cylinder (Right)	Oil leakage moderately
	Attachment	Looseness	Arm cylinder	X
	Swing/ Offset	_	Bucket cylinder	X
	Dozer	_	Swing/ Offset cylinder	_
			Dozer Cylinder	_
Operation	Operation lever	Х	Boom	X
	Travel lever	Х	Arm	Х
	Swing	Χ	Attachment	X
	Travel	Χ	Swing/ Offset	_
	Retracted Crawlers	_	Dozer	_
	Shoe	Х	Crawler Frame	Rusty
Undercarriage (Left)	Link / Bushing	Wear moderately	Upper Roller	Х
	Idler	Х	Lower Roller	Х
	Travel Reduction Unit/ Motor	Χ	Sprocket	X
Undercarriage (Right)	Shoe	Х	Crawler Frame	Rusty
	Link / Bushing	Wear moderately	Upper Roller	X
	Idler	Х	Lower Roller	X
	Travel Reduction Unit/ Motor	Χ	Sprocket	X
Electrical equipment	Error	Х	Gear Change	X
	Monitor	X	Battery	X

Important Notice

wiper blade missing

crane mode troubled (exact number not shown)