

INSPECTION REPORT for Excavator 検品書 (油圧ショベル)

Maker	KOBELCO	Model	SK2	8-00	Serial		YN11-52248	
Year	2008	Hour	8,441	hr/	OK B	KT/ATT	Bucket	Without BKT
Shoe	600 ^{mm}		Steel	Piping			_	
Multi Control	Multi			Air Conditioner	AC			
Dozer	_ ID key V	/ith (W	ithout master)	Crane			With	
Operator Seat	CAB			Accessories				
Specification								

	Subject	Condition	Subject	Condition
Engine	Start/ Stop	Χ	Accell	Χ
	Output	Х	Sound	Χ
	Exhaust Gas	Х	Oil Leakage	Χ
	Blow-by Pressure	Х	Fuel Leakage	Χ
	Radiator	Х	Oil	Χ
Hydraulic	Pump Output	Х	Control Valve	Х
	Sound	Х	Oil Cooler	Χ
Cuina	Swing bearing/ Gear	X	Swing Reduction Unit/ Motor	Х
Swing	Swivel Joint	Х	Swing Reduction Unit Oil	Х
Attachment	Boom	Looseness	Boom cylinder (Left)	Х
	Arm	Χ	Boom cylinder (Right)	Χ
	Attachment	Looseness	Arm cylinder	Χ
	Swing/ Offset	_	Bucket cylinder	Scratch
	Dozer	_	Swing/ Offset cylinder	_
			Dozer Cylinder	-
Operation	Operation lever	Х	Boom	Х
	Travel lever	Х	Arm	Х
	Swing	Х	Attachment	Х
	Travel		Swing/ Offset	_
	Retracted Crawlers	_	Dozer	-
Undercarriage (Left)	Shoe	Breakage	Crawler Frame	Rusty
	Link / Bushing	Х	Upper Roller	Х
	Idler	Spring breakage	Lower Roller	Χ
	Travel Reduction Unit/ Motor	Χ	Sprocket	Χ
Undercarriage (Right)	Shoe	X	Crawler Frame	Rusty
	Link / Bushing	Х	Upper Roller	X
	Idler	Spring breakage	Lower Roller	Χ
	Travel Reduction Unit/ Motor	X	Sprocket	Χ
Electrical	Error	X	Gear Change	Х
equipment	Monitor	Х	Battery	Χ

Important Notice

air conditioner troubled

1 left shoe plate bent

crane mode troubled (around -0.3t error)