

INSPECTION REPORT for Excavator

検品書 (油圧ショベル)

Maker	KOBELCO	Model	SK200-9	Serial	YN13-70072
Year	2013	Hour	8,229 hr/	OK	BKT/ATT
Shoe	600 mm	Steel	Piping	Crusher and Breaker piping	
Multi Control	Multi	Air Conditioner	AC		
Dozer	—	ID key	With (Without master)	Crane	With
Operator Seat	CAB	Accessories			
Specification					

	Subject	Condition	Subject	Condition
Engine	Start/ Stop	X	Accell	X
	Output	X	Sound	X
	Exhaust Gas	X	Oil Leakage	X
	Blow-by Pressure	X	Fuel Leakage	X
	Radiator	X	Oil	X
Hydraulic	Pump Output	X	Control Valve	X
	Sound	X	Oil Cooler	X
Swing	Swing bearing/ Gear	X	Swing Reduction Unit/ Motor	X
	Swivel Joint	X	Swing Reduction Unit Oil	X
Attachment	Boom	Looseness	Boom cylinder (Left)	X
	Arm	Looseness	Boom cylinder (Right)	X
	Attachment	Looseness	Arm cylinder	X
	Swing/ Offset	—	Bucket cylinder	X
	Dozer	—	Swing/ Offset cylinder	—
			Dozer Cylinder	—
Operation	Operation lever	X	Boom	X
	Travel lever	X	Arm	X
	Swing	X	Attachment	X
	Travel	X	Swing/ Offset	—
	Retracted Crawlers	—	Dozer	—
Undercarriage (Left)	Shoe	Breakage	Crawler Frame	Concrete adhesion
	Link / Bushing	X	Upper Roller	X
	Idler	Spring breakage	Lower Roller	X
	Travel Reduction Unit/ Motor	X	Sprocket	X
Undercarriage (Right)	Shoe	Breakage	Crawler Frame	Concrete adhesion
	Link / Bushing	X	Upper Roller	X
	Idler	X	Lower Roller	X
	Travel Reduction Unit/ Motor	X	Sprocket	X
Electrical equipment	Error	X	Gear Change	X
	Monitor	X	Battery	X

Important Notice

with rear view monitor